

~~SECRET~~

CIA RDP81B00879R001000130005-6

DOCUMENT NO.
NO CHANGE IN CLASS.
DECLASSIFIED
CLASS. CHANGED TO: TS
NEXT REVIEW DATE: 20/12
AUTH: HR 70-2
DATE: 16/12/82 REVIEWER

OXC 6217
Copy of 8

23 DEC 1963

25X1

MEMORANDUM FOR: Chief, OXCART, OSA

25X1A

SUBJECT: Capability

25X1A

REFERENCE: Memorandum from C/COMMO/OSA to
C/OD/OSA; dated 16 Dec 63; Subject:
Results of Meeting between FAA, USAF
and - 10 Dec 63
(OXC 6205) Attached

25X1A

25X1A


25X1A

1. Request you collect all pertinent information on the current status of reference equipment, including schedule of follow-on actions planned, estimated operational ready date, limitations, etc. Further request you brief me on the above material at the earliest opportunity but NLT 27 December 1963.

2. I somehow have missed the continuity of the plans, development and actions during recent months and the reasons therefore. The principal concern uppermost in my mind today is why do we not have a current capability? In other words, why did we move the equipment from (where we had a capability) to
 especially before we (obviously) were nearly ready to get it in operation there? Who made the decision? Did we lose control of it? As you know the entire idea generated right here as a Headquarters/operational requirement, and it was studied, procured, installed, checked and coordinated under our direction. It was agreed that we might and probably would want additional sets for other locations later.

3. Please bring me up to date and let's discuss where and how we are going to keep control over such items.

25X1A



Lt. Colonel USAF
AD/FA/OSA

Attachment - 1

Ref as stated

Approved For Release 2003/02/27 : CIA RDP81B00879R001000130005-6

~~SECRET~~

SECRET

25X1A

AD/FA/OSA/ [redacted] clp (23 Dec 63)

Distribution:

- #1 - OXC/OSA (w/att)
- #2 - D/TECH/OSA (wo/att)
- #3 - COMMO/OSA (wo/att)
- #4 - MD/OSA (wo/att)
- #5 - D/FA/OSA (wo/att)
- #6 - AD/FA/OSA (wo/att)
- #7 - RB/OSA (wo/att)
- #8 - Holdback (wo/att)

SECRET